


NO.
0387PRO Wear CARE sweatshirt | hoodie |
women

Description (measured in cm)	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL
A: 1/2 Chest width	47	50	53	57	61	64	67	71	75	79
E: Front length from high point shoulder	64.5	66.5	68.5	70.5	72.5	74.5	76.5	78.5	80.5	82.5
H: Shoulder to shoulder	39.5	41	42.5	44.5	46.5	48.5	50.5	52.5	54.5	56.5
K: Sleeve length - long	61	62	63	64	65	66	67	67	67	67
L: 1/2 upper arm width	17.5	18.5	19.5	20.5	21.5	22.7	23.9	25.1	26.3	27.5

How to measure



Tolerance in cm

A	E	H	K	K2	L
1.5	1.5	1.5	1.5	1	1

The measurements in a product measurement chart refer to measurements made directly on the clothing. Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not after washing. We reserve the right to make mistakes and omissions in the chart. You are always welcome to contact us for further guidance on using our product measurement chart at support@id.dk or tel: +45 97492144