


NO. 0613 Sweatshirt | business



Description (measured in cm)	S	M	L	XL	2XL	3XL
A: ½ Chest width	55	58	61	64	67	70
E: Front length from high point shoulder	70	72	75	77	79	81
K1: Sleeve length from high shoulder point - long	78	81	83	86	87	88
L: ½ upper arm width	23	24	25	26	27	28

How to measure



Tolerance in cm

A	E	K1	K3	L
1.5	1.5	1.5	1	1

The measurements in a product measurement chart refer to measurements made directly on the clothing. Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not after washing. We reserve the right to make mistakes and omissions in the chart. You are always welcome to contact us for further guidance on using our product measurement chart at support@id.dk or tel: +45 97492144