

Article: 0370 - PRO wear CARE - Men's O-neck

Size		XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL	Sample	Tolerance
A	½ Chest, Armpit to Armpit	47,00	50,00	53,00	56,00	59,00	62,00	65,00	69,00	73,00	77,00		+/-1.5
E	Length from HPS, front	69,00	71,00	73,00	75,00	77,00	79,00	81,00	83,00	85,00	87,00		+/-1.5
H	Shoulder to Shoulder	44,50	45,50	47,00	48,50	50,00	51,50	53,00	55,00	57,00	59,00		+/-1.5
K	Sleeve Length, SS	20,50	21,00	21,50	22,00	22,50	23,00	23,50	24,00	24,50	25,00		+/-1
L	½ Upper arm width	18,00	19,00	20,00	21,00	22,00	23,00	24,25	25,50	27,00	28,50		+/-1

All measures are in centimeters (cm.)

How to measure - not for design
hps = high point shoulder

