


[

NO. 0830 Rain jacket | performance



Description (measured in cm)	S	M	L	XL	2XL	3XL
A: ½ Chest width	53	56	60	64	67	70
E: Front length from high point shoulder	76.5	78.5	80.5	83	85.5	88
H: Shoulder to shoulder	45	46.5	48.5	50.5	52.5	54
K: Sleeve length - long	67.25	68.25	69	71	73	74.5
L: ½ upper arm width	21	22	23	24	25	26

How to measure



Tolerance in cm

A	E	H	K	L
1.5	1.5	1.5	1.5	1

The measurements in a product measurement chart refer to measurements made directly on the clothing. Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not after washing. We reserve the right to make mistakes and omissions in the chart. You are always welcome to contact us for further guidance on using our product measurement chart at support@id.dk or tel: +45 97492144